

# IDEA 3.5.235 Readme File

README for Foresight Imaging IDEA V3.5.235, October 3, 2022

This release is provided as an online download or on a single CD for Windows 10 64 bit operating systems.

IDEA v3.5.235 for 64 bit OS, CD part number: 042700-352

Please note that product documentation is provided in electronic format only.

You will need the Adobe Acrobat Reader version 8.0 or higher to view the documentation.

Adobe Acrobat can be downloaded at either:

[www.adobe.com](http://www.adobe.com) or [www.fi-llc.com](http://www.fi-llc.com)

The IDEA software and hardware installation manuals are located on the CD and in the **C:\Program Files\Foresight\IDEA\Doc** directory (after installation) as SDK\_Manual.pdf & Install\_Manual.pdf.

A demonstration version of the Accusoft / Pegasus Imaging MJPEG codec is included for use with the example programs.

For information on licensing this software, please go to:

<https://www.accusoft.com/products/picvideo-m-jpeg-codec/overview/>

IDEA\_AV Active X Demo, StreamCap and IDEADemo API Example Program are the three example programs recommended for use to evaluate the full functionality of the frame grabbers and video streamers. MultiCard can be used if you are using more than one capture card. They are included in: [Start || Foresight Imaging](#).

StreamCap is the DirectShow demonstration program that uses the IDEA WDM AVStream driver. It is located in the C:\Program Files\Foresight\idea\Demo\Bin folder.

Recommended WDM capture software:

An excellent WDM recording software program, Debut Video Capture application is available from NCH Software. With the IDEA WDM driver and this software, streaming video to disk is accomplished in a matter of minutes. For information and downloading,

go to: <http://www.nchsoftware.com/capture/index.html>

=====

\*\*\*\*\* **Release Notes** \*\*\*\*\*

=====

IDEA 3.5.235 is a full release package which supersedes all previous IDEA versions.

-Note: the full IDEA revision information is available under Windows Control Panel, 'Programs and Features' or 'Add or Remove Programs'

**IDEA 3.5.235 Changes:**

All:

- Fixed a problem in the device driver where the on-board EEPROM could be erased if an application that used DirectShow accessed the device driver at the same time as an IDEA application was starting.

**IDEA 3.5.233 Changes:**

All:

- Fixed a DMA problem that gave incorrect pixel data near the end of a line if the width in pixels was not divisible by 16.

**IDEA 3.5.232 Changes:**

All:

- Fixed Y-only DMA problem where the last 6 pixels of each line was set to zero. Autosync uses this mode for the 4-panel view.
- Added a dialog to give the user the opportunity to shut down the system after a gate array flash update.
- Fixed problem in speed up optimizations of RSET\_Set() that caused AutoSync pixel detect to make errors on some formats and incorrectly set Hue in YPbPr formats.

**IDEA 3.5.231 Changes:**

All:

- Added ability to disable the DVI and HDMI cable extenders on the HD+. Chp file entries in the [I- RGB] section, DVICableExtender = 0 or 1 and HDMICableExtender = 0 or 1.
- Fixed capture failure with AccuStream Express 170 capture introduced in 3.5.225.
- Fixed a problem where capturing a video format of a smaller size than specified by the CHP file could cause a system crash.
- S-Video did not show sync detected in some programs.
- Accustream 1000 frame rate control was not working correctly for interlaced signals.

DirectShow:

- Fixed problem in Accustream 1000 where some interlaced signals would fail to AutoDetect.
- Fixed framing problem with interlaced analog video signals..

**IDEA 3.5.225 Changes:**

All:

- Fixed brightness and contrast adjustment and improved update rate.

- Gate array update. Fixed a problem where DMA would hang if lines past vertical sync were requested as can happen in AutoSync when adjusting Vertical Back Porch.

DirectShow:

- Fixed capture and display DMA which stopped working after gate array change in .224.

#### **IDEA 3.5.224 Changes:**

All:

- Fixed an error where 24-bit captures resulted in distorted images when the width was not a multiple of 16 pixels.
- Fixed an error in sync detection for the AccuStream Express 170.
- Fixed an error in interlaced sync detection for the AccuStream Express 1000.
- Changed AccuStream Express 1000 primary trigger input from the ring to the tip so a standard BNC to 3.5mm tip & sleeve 2-conductor cable can be used in a single trigger application.

ActiveX control:

- Fixed Area of Interest capture.

#### **IDEA 3.5.220 Changes:**

All:

- Fixed an error in sync detection where if composite sync moved from one analog channel to another the change wasn't detected.

#### **IDEA 3.5.219 Changes:**

All:

- Fixed an AS1000 error where AutoSync created a format for monochrome analog composite sync signals that was too narrow.

#### **IDEA 3.5.218 Changes:**

All:

- Fixed an AS1000 frame dropping problem.
- Fixed an AS1000 error with frame rate measurement.
- Improved AS1000 FPGA timing margins.
- Added back ASHD+ S-Video detection accidentally disabled in a previous release.
- Fixed an AS1000 error where StreamCap would fail on VGA type input signals during the AutoDetect operation.

#### **IDEA 3.5.217 Changes:**

All:

- Fixed an error where if a smaller digital format was input when a larger format was selected the frame rate dropped to less than 1 FPS and only the first line of video was captured.
- Fixed an error where if display or capture was running and the input signal was removed from the Accustream 1000 the system would sometimes lock up or blue screen.

### **IDEA 3.5.214 Changes:**

All:

- Fixed error in eHP\_GetControlValue("SignalInfo") that caused AutoSync to not show Input Selection dialog if one of the inputs was monochrome.
- Added optimization to RSET\_Set() to skip checking for sync on completion when only simple image adjustments are done. Speeds up AutoSync adjustments.
- Fixed an error where some VGA formats were incorrectly being detected as interlaced.

AutoSync:

- The "Center Image" button caused system crash.

### **IDEA 3.5.211 Changes:**

All

- Added adjustment of HDMI pixel frequency measurement when the pixel repetition value is not 0. Was not working correctly on 480i and 576i formats.
- Added IDEA\_INFO\_CONNECTION message to the IDEA\_INFO event to indicate sync status changes on all but the selected input. Event now returns SYNC\_INFO in the pInfoObject of IDEA\_INFO\_EVENT.
- Fixed error in eHP\_GetControlValue("SignalInfo") that caused AutoSync to not detect sync on some digital signals.
- Added DVIHotPlug and HDMIHotPlug to eHP\_SetControlValue() and eHP\_GetControlValue() to allow a user to set and get the state of these signals.

### **IDEA 3.5.210 Changes:**

All

- Made timing improvements in sync loss detection.
- Fix to AccuStream 1000 gate array to eliminate 16 byte aligned start address requirement.
- Fix for AccuStream 1000 DMA where lines wider than 1920 could make address errors.
- Calls to eHD\_GetControlValue() for CurrentSignalInfo and SyncInfo now return copies of internal structures rather than reading hardware registers. Registers are now read in a background IDEA thread to allow IDEA to control when the reads occur. This prevents operational conflicts caused by asynchronous hardware accesses.
- Fixed an I2C register read problem caused by long PCIe read latency. This has been seen in some systems especially if a board is in a slot connected through a bridge
- Corrected AccuStream 1000 SDI interface, interlaced was only capturing one field.

AutoSYNC:

- AccuStream 1000 AutoSync YPbPr video framing improvements.

ActiveX control:

- Fixed JPEG file save, had red and blue swapped.

### **IDEA 3.5.102 Changes:**

All:

- Rotate was not working for 32-bit pixel types.

API:

- Fixed a problem where bHP\_CSsyncDetect() execution time increased dramatically from 3.4.416.

- Fix for Block Sync Formats (No horizontal sync during vertical sync) where image moved up and down by 1 line. If Block Sync setting in AutoSync Miscellaneous tab doesn't work, try Extended Block Sync. This change only takes effect when Vertical Sync Type is not set to normal.
- Added logging.

ActiveX control:

- Frame rate control using frame decimation did not set the AVI file frame rate correctly.

Driver:

- Fixed an error where on very rare occasions the driver would return a hardware registers pointer of zero which would cause the calling application to crash.

DirectShow:

- Sync was not detected with AutoDetect turned off and a VGA type format file selected.

AutoSYNC:

- Fixed error where input selection dialog would not display when more than one input signal was connected.

StreamCap DirectShow Demo:

- Status bar capture time was incrementing while waiting for trigger. Now holds at zero until trigger event.

IdeaDemo API Demo:

- Snapshot saves were being written to the application folder not the pictures folder.
- Live display scaling was not sized properly
- Snapshot taken when Live Display was stopped was sometimes be black.

### **IDEA 3.5.101 Changes:**

All:

- All programs had a slight AVI frame rate error when the rate was not a whole number. Fixed by increasing the precision of the rate.

API:

- Added logging.
- Fixed a problem where bHP\_CSsyncDetect() would sometimes not report the correct sync state..

Driver:

- Fixed an error where on very rare occasions the driver would return a hardware registers pointer of zero which would cause the calling application to crash.

Demos:

- Improved C# demo.

### **IDEA 3.5.100 Changes:**

API:

- Fixed a problem where bHP\_CSsyncDetect() execution time increased dramatically from 3.4.416.
- Fix for Block Sync Formats (No horizontal sync during vertical sync) where image moved up and down by 1 line. If Block Sync setting in AutoSync Miscellaneous tab doesn't work, try Extended Block Sync. This change only takes effect when Vertical Sync Type is not set to normal.
- Added support for streaming to Nvidia GpuDirect.

- Added IdeaGpuDemo to demonstrate using IDEA with Nvidia GpuDirect.

### **IDEA 3.5.033 Changes:**

All:

- Added support for the new AS1000 and AS2000 boards.
- Temperature logging command added to SetControlValue()  
eHP\_SetControlValue(0, "LogTemperature", sizeof(LogTemperature), &LogTemperature);

```
typedef struct
{
    char *pszLogFile;           // If null messages are written to default
IdeaTemperatureLog.txt
    BOOL bLogTemperature;
    int nTemperatureLogSeconds; // If 0 log interval is 60 seconds.
} LOG_TEMPERATURE;
```

DirectShow:

- Added temperature display and logging in the Capture Filter Properties Dialog.

Demos:

- Added a C# demo called IdeaDemo.Net. The demo includes interface examples for IDEA API, IDEA ActiveX and DirectShow operation.

### **IDEA 3.4.420 Changes:**

All:

- Fixed a problem where bHP\_CSsyncDetect() execution time increased dramatically from 3.4.416.
- All programs had a slight AVI frame rate error when the rate was not a whole number. Fixed by increasing the precision of the rate.
- Rotate was not working for 32-bit pixel types.

API:

- Fixed a problem where bHP\_CSsyncDetect() would sometimes not report the correct sync state..
- Fix for Block Sync Formats (No horizontal sync during vertical sync) where image moved up and down by 1 line. If Block Sync setting in AutoSync Miscellaneous tab doesn't work, try Extended Block Sync. This change only takes effect when Vertical Sync Type is not set to normal.

ActiveX control:

- Frame rate control using frame decimation did not set the AVI file frame rate correctly.

Driver:

- Fixed an error where on very rare occasions the driver would return a hardware registers pointer of zero which would cause the calling application to crash.

DirectShow:

- Sync was not detected with AutoDetect turned off and a VGA type format file selected.

AutoSYNC:

- Fixed error where input selection dialog would not display when more than one input signal was connected.

StreamCap DirectShow Demo:

- Status bar capture time was incrementing while waiting for trigger. Now holds at zero until trigger event.

IdeaDemo API Demo:

- Snapshot saves were being written to the application folder not the pictures folder.
- Live display scaling was not sized properly
- Snapshot taken when Live Display was stopped was sometimes be black.

### **IDEA 3.4.418 Changes:**

All:

- All SDK examples and core software is built using Visual Studio 19

Driver:

- Added system sleep wake handlers to allow support of Windows 10 Fast Startup..

API:

- Fixed a problem where bHP\_CSsyncDetect() could report valid sync momentarily after HDMI cable disconnected.
- Fixed a false sync detection problem caused by an HDMI splitter that incorrectly generated a clock signal when its input signal was disconnected.

AutoSYNC:

- Fixed error where color mode selection was not preserved from run to run even though the user interface showed it was.
- Fixed error where systems with greater than 4GB of memory could experience a "Could not lock DMA buffer" error.
- Moved hdperror.dat to the Idea\System folder because it was missing if the SDK was not installed. Caused AutoSync logs to show errors where there were none.

ActiveX control:

- Corrected problem call to Snap() would hang waiting for trigger. Snap is now done in a new thread if trigger is enabled.

Idea\_AV demo:

- Added trigger button to allow triggered snapshots to be done from the user interface.

Installer:

- Fixed a problem when installing over an older version of Idea where the Microsoft installer would show error 1603 after uninstalling the old version.

Twain:

- Updated to work correctly with Windows 10 file location security restrictions. Moved .ini files to C:\Users\Public\Documents\Foresight\Twain.
- Added 64-bit Twain DataSource.
- Installer now installs the newer TWAINDSM.DLL files for both 32 and 64-bit applications. 32-bit DataSource still uses the older twain\_32.dll by default but can be set

to use the newer 32-bit TWAINDSM.DLL by setting UseNewTwainDsm32Dll=1 in IdeaTwain.ini.

### **IDEA 3.4.416 Changes:**

#### AutoSYNC:

- Aspect Ratio Tool settings are saved across sessions.
- Input selection dialog is not shown if there is only 1 active input.
- Input selection dialog remembers last choice.
- Color mode selection dialog remembers last choice.

#### DirectShow::

- Made "don't show error dialogs" the default setting. Error dialogs can be turned back on in the Capture Filter properties dialog.

#### CHP Files::

- Added European HDTV formats to the VideoFormats\HDTV folder.

#### Installer:

- Default installation does not include SDK. SDK feature must be selected at installation time. Silent install does not include SDK.
- Install\_IDEA.exe install launcher has been updated to allow several installation options. There are .bat files to show how to use them.

#### Command Line **Parameters:**

Passing no parameter will launch setup.exe then Install\_IDEA will exit to get out of the way.

**silent** – calls setup.exe with /s /wait\_clone, generates log files in the users temp folder c:\Users\User\AppData\Local\Temp.

**hide** – makes launcher window invisible. can be combined with silent and uninstall.

**record** – creates/overwrites setup.iss in the 64\Scripts folder (32\ if 32 bit o/s). Use this only if silent option is not working for you.

**uninstall** - uninstalls currently installed instance of IDEA.

To run Install\_IDEA from inside an application use "start /wait Install\_IDEA.exe silent".

### **IDEA 3.4.414 Changes:**

#### DirectShow::

- Fixed a problem where the DirectShow driver did not release a board claim until the application using it was closed. Caused unexpected board in use messages.

#### AutoSYNC:

- With DVI/HDMI video sources, three separate monochrome channels are now created: CA1, CA2 & CA3.

(In 3.4.411 & 3.4.412, only CA1 monochrome was created corresponding to the RED channel).

#### Installer:



- Installer does a full uninstall if a previous IDEA version is found.

General:

- Fixed error in the 32 bit API DLL where addresses above 2G would cause a lock error to occur during eHD\_LiveStreamInit() on a 64 bit system .

**IDEA 3.4.412 Changes:**

General::

- Fixed a problem that caused streaming to become and stay erratic when CPU load nears 100%.

**IDEA 3.4.411 Changes:**

WDM AVStream driver:

- Fixed a problem that on rare occasions caused a blue screen crash during streaming.
- Added more exception handling to allow driver to shut down streaming if a user application exits without stopping streaming properly.

AutoSYNC:

- Added circle matching tool to assist in the image tuning process of Fluoroscope video where AutoSYNC is not able to determine the pixel frequency.

ActiveX control:

- Corrected problems changing contrast and brightness through the API.
- Added a Dialog Action Event AOI\_DIALOG\_NOTIFY for Area Of Interest changes made through the AOI property page..

General:

- Fixed error in Auto Format Detection to prevent a YPbPr file from being used for an RGB signal.

**IDEA 3.4.410 Changes:**

Driver for Windows 10 Secure Boot:

For Windows 10 the setup.exe will install the driver from the "Driver - Win10 Secure Boot" folder on the installation media.

For Windows 7 the driver from either \64\Drivers or \32\Drivers will be installed.

API Additions: Contact Foresight for more information.

- eHD\_AutoDetect()
- eHD\_SetInfoEvent()
- eHD\_ResetInfoEvent()

**IDEA 3.4.409 Changes:**

WDM AVStream driver:

- Fixed a problem that caused a blue screen crash during streaming.

**IDEA 3.4.408 Changes:**

WDM AVStream driver:

- Fixed a problem where in some applications the frame rate control code caused a blue screen crash.

StreamCap DirectShow Demo:

- Disabled Preview live video when showing properties dialog to prevent crash when format changes..

#### **IDEA 3.4.408 Known Issues:**

APIDemo.net:

- Uses old AVI 1.0 methods to write a video file. May produce distorted video on Windows 10. Will be fixed in a later release.

#### **IDEA 3.4.407 Changes:**

ActiveX control:

- Snap cancel fixed to prevent lockup on trigger event occurring after a snap is cancelled.

WDM AVStream driver:

- Added frame rate control to both the capture and preview pins.

StreamCap DirectShow Demo:

- Added frame rate control to both the capture and preview pins settings.

General:

- Added detection for HDMI and DVI Pixel Repetition Mode when pixel clock rate is multiplied because pixel rate is too low for TMDS signaling.

#### **IDEA 3.4.406 Changes:**

AutoSYNC:

-With DVI video sources, three separate monochrome DVI channels are now created: CA1, CA2 & CA3. (Previously, only CA1 monochrome was created).

General:

-When switching from a Digital to Analog source, the analog capture would result in black or corrupted images, this is now resolved. (Applies to AccuStream Express 170 & AccuStream 170+ only)

===

#### **IDEA 3.4.405 Changes:**

General:

DVI/HDMI Hot-plug detect "AlwaysOn" added as an option for HD+ and HD+C boards. This will prevent problems seen in some DVI/HDMI splitters where Hot plug detect reacts very slowly to input changes.

HD+C codec firmware corrected to include CPB (Coded Picture Buffer) delay setting.  
Foresight 1920x1080.dat EDID file video timing corrected.  
HD+C automatically inserts "No Video" message into stream on loss of sync.  
Corrected some initialization timing problems seen on new systems especially running Win 10.  
Added exception handling to DirectDraw and Direct2D buffer handling to prevent crash if surface memory address goes invalid while displaying live video.

#### WDM Capture Driver:

Added Streaming triggered start.

Resolved an issue where if the video source was disconnected and reconnected while capture image trigger was enabled and active live video display would not display upon video reconnection.

#### ActiveX control:

Improved handling for live video recovery after returning from Windows Screen Saver or Login screen.

### **IDEA 3.4.3 Changes:**

#### General:

Windows 10 Support

HD+C will continue streaming a "No Video" message frame when the video signal is removed, if enabled to do so.

When the IDEA release contains new Gate Array programming files, as this one does, you will no longer have the option to skip updating. After the flash memory programming is completed the system must be powered off and back on again for the update to take effect. The power off/on is now required because many newer systems will either blue screen crash or disable the mapping of the board's register area if the PCIe interface gets disabled, which happens when the gate array loads from flash memory. The mapping will not get re-enabled until the next power on.

Minor improvements for the AccuStream 170+ and AccuStream Express 170 on recovering from signal loss/re-connection on some DVI formats.

#### Board Gate Array Firmware changes:

Correct sync decoding where composite sync is generated by Exclusive OR of H & V syncs, on the Express family of boards. Addition of "No Video" handling in HD+C.

#### Driver:

Better handling of low memory conditions which can happen if Virtual Memory is disabled. In some cases, this condition caused a system crash in previous versions.

#### WDM Capture Driver:

Improvements to AVStream capture to be compatible with more DirectShow applications and WebRTC.

Sync status indicator made more reliable.

#### CHP changes:

Addition of VideoWidth and VideoHeight parameters to define the width and height of the full video signal when ImageWidth and ImageHeight are used to define an area of interest. This is needed for the HD+C board to continue delivering a video stream when there is no video signal connected.

#### AutoSYNC:

Added Image Rotation control for all signals and Clamp position adjustment for analog signals.

#### IdeaAVI DLL:

Retains compatibility with previous versions but adds the capability to instantiate an IdeaAviFile object to allow multiple boards to have their own instance of the AVI file writer.

Create a new instance using:

```
CideaAviFile* CreateInstance(CWnd* pParent)
```

IdeaAviMP DLL is deprecated but included for legacy compatibility

#### MultiBoard Demo:

Changed to Use IdeaAVI DLL instead of IdeaAVIMP DLL.

#### API Changes:

Structure and parameter changes. See hpd\_lib.h in the Idea\include folder.

Structure members added to the LIVESTREAM\_INFO structure.

API detects new structure from increased structure size, dwSize must be set properly.

DWORD dwTriggerStartFrameDelay	Frames after start trigger where capture starts
DWORD dwTriggerStopFrameDelay	Frames after stop trigger where capture stops

HD+C now responds to changes in H.264 Profile and Level where "Auto" was the only setting available on previous versions.

Profile can be "HIGH", "MAIN" or "BASELINE"

Level can be from 1 to 4.2. Depends on resolution rate. See a description online of H.264 levels.

To enable HD+C to continue streaming a "No Video" message frame when the video signal is removed:

```
DWORD dwValue = 1; // 0 to disable
eHP_SetControlValue(BoardHandle, "InsertMessageFramesOnLossOfVideo",
sizeof(DWORD), &dwValue);
```

To force HD+C to show the "No Video" message frame:

```
DWORD dwValue = 1; // 0 to return to normal
eHP_SetControlValue(BoardHandle, "ShowMessageFrame",
sizeof(DWORD), &dwValue);
```

To get information about the currently connected video signal:

```
SIGNAL_INFO SignallInfo;
memset(&SignallInfo, 0, sizeof(SignallInfo));
SignallInfo.dwInfoSize = sizeof(SignallInfo);
SignallInfo.dwMode = 1;
eHP_GetControlValue(g_BoardHandle, "CurrentSignallInfo",
sizeof(SIGNAL_INFO), &SignallInfo);
```

To get information about the signals connected to all the video inputs:

```
SYNC_INFO SyncInfo;
memset(&SyncInfo, 0, sizeof(SYNC_INFO));
SyncInfo.dwInfoSize = sizeof(SYNC_INFO);
eHP_GetControlValue(g_BoardHandle, "SyncInfo", sizeof(SYNC_INFO), &SyncInfo);
```

ActiveX control:

Live video display restarts after desktop switch or resolution change.

IdeaDemo:

Live video display restarts after desktop switch or resolution change.

### **IDEA 3.4.2 Changes:**

Driver changes:

Corrected error in DMA buffer unlock where a zero pointer caused a blue screen crash.

### **IDEA 3.2.1 Changes:**

CHP changes:

Rotate command added to the I-RGB section. Values = None, Left, Right

API changes:

Structure and parameter changes. See hpd\_lib.h in the Idea\include folder.

Structure members added to the COMPRESSION\_INFO structure.

API detects new structure from increased structure size, dwSize must be set properly.

szH264GopStructure, values = IBBP, IBP, IPPP

bH264OpenGoop, values = FALSE, TRUE.

bH264DisableTimebaseCorrector, values = FALSE, TRUE.

dwH264CodedPictureBufferDelay, values = 50 – 500 (milliseconds)

dwOutputFrameRate now functioning.

Minimum compression DMA buffer size reduced from 4096 to 1024 bytes.

HPR\_FLAGS\_ROTATE\_LEFT & HPR\_FLAGS\_ROTATE\_RIGHT added to HPR\_FLAGS member of RSET

HDXFR\_PIXEL\_BGR888\_24, HDXFR\_PIXEL\_BGR888\_32 & HDXFR\_PIXEL\_BGR555\_16 pixel types added to all transfer calls.

ActiveX control:

Common Configuration for All Users checkbox added to configuration dialog. Previously configurations were saved only on a per user basis. This allows one configuration regardless of user login.

Target Frame Rate control added to Configuration Streaming tab. Allows precise output frame rate control.

Parameters added to H.264 Configuration:

Timebase corrector disable. Enabled is recommended. Disable control provided in case an encoding timebase problem is suspected.

GOP type, Open or Closed – Closed is default.

GOP structure, IBBP, IBP and IPPP – IBBP is default

Coded Picture Buffer Delay, 50ms – 500ms – 100ms default

DirectDrawCopy added to Live Video type to allow DirectDraw emulation on Windows 7 and above with systems that don't support hardware DirectDraw support.

All parameters saved to the registry on a using PCI slot number rather than board serial number.

Record Audio to WAV file.

New Properties:

- long H264OutputFrameRate
- long StreamingFrameRate (AVI and memory)
- booleanH264TimebaseCorrectorEnable
- booleanH264OpenGop
- long H264CodedPictureBufferDelay
- BSTR H264GopStructure

New Methods:

- long GetTriggerState()
- booleanStreamToMemoryAtRate(long FrameCount, long Flags, long, StartEvent, long PauseEvent, long CancelEvent, long\* MemoryHandle, long FrameRateX100)
- booleanStreamToAviAtRate(long FrameCount, long Flags, long, StartEvent, long PauseEvent, long CancelEvent, long\* MemoryHandle, long FrameRateX100)
- booleanStreamToDicomAtRate(long FrameCount, long Flags, long, StartEvent, long PauseEvent, long CancelEvent, long\* MemoryHandle, long FrameRateX100)

Autosync changes:

- Temperature measurement added to About dialog box.

MultiBoard Demo:

- Added ability to record separate AVI file or MPG file per board, up to 4.

WDM driver:

- Added frame rate control to output pins.

===

## **INSTALLATION:**

- To install IDEA 3.5 on a system:

- Un-install any previous versions of IDEA in Windows Control Panel, Add/Remove Programs.

Run the **Install\_IDEA.exe** or one of the batch files file in the root directory.

Follow the prompts to complete the installation.

## **UPGRADING Applications to IDEA 3.5**

=====

- \* If your application is based on an earlier version of IDEA than IDEA 3.4 it must be recompiled and re-linked using the new IDEA 3.5 libraries, header files, & OCX wherever applicable.
- \* Updating only the IDEA DLL's and drivers from a pre-3.4 release without rebuilding the application will result in unstable operation.

## **Supported:**

=====

- \* Windows 10 All Editions.
- \* Foresight Imaging frame grabbers and video streamers:  
AccuStream Express 170, AccuStream Express 75, AccuStream Express 50  
AccuStream Express HD+, AccuStream Express HD 75+, AccuStream Express SD 50+  
AccuStream 1000, AccuStream 2000
- \* DVI-D Single link signals only, (DVI-D Dual link is not supported)

## **CONTENTS:**

=====

This CD-ROM or file download contains:

- \* IDEA 3.5 SDK and Demo files in the setup directory
- \* AutoSYNC video configuration & measurement tool
- \* The IDEA installation and SDK manuals in PDF format
- \* Pegasus compression software for streaming to disk demo (AVI file creation)
- \* StreamCap application program an example to stream large video files.
- \* The unpacked IDEA library contains the IDEA software, Demos, Documents, and Windows Drivers.

## **Updates to Documentation**

=====

The included documentation is for the V3.5 software release. Additions to functionality are documented above in the **Important Changes** section.

## **MINIMUM SYSTEM REQUIREMENTS:**

=====

- \* Intel Core processor or better
  - \* Windows 10
  - \* Memory: minimum 512 MB
  - \* Appropriate video source
  - \* High quality input video cabling
  - \* PCIe x4 bus
  - \* Administrator rights are required to install the IDEA SDK & software.
- \*\*\* Note: For RGB signals, please ensure that the cable lengths are identical for all connections.  
A bundled RGB and sync cable is recommended.

## **Other Notes:**

=====

- 1) The Accusoft / Pegasus Compression CODECS are available at  
<https://www.accusoft.com/products/picvideo-m-jpeg-codec/overview/>




2) For AVI file playback, the latest version of Windows Media Player is available at: <https://www.microsoft.com/en-us/search/result.aspx?q=windows+media+player>, Virtual Dub: <http://www.virtualdub.org>, VLC: <http://www.videolan.org>

### Gate Array Messages:

- The gate array firmware on the AccuStream Express, AccuStream HD+ & AccuStream HD+C series of boards comes programmed from the factory.
- This gate array firmware can be updated in the field on new IDEA software updates.

-Upon invoking an IDEA application, an “**IDEA Gate array configuration**” message may appear, similar to:



This is not an error message, but an indication the programmed firmware on the AccuStream board is not the same version as the files in IDEA software.

The revision is in a date format of **YYYYMMDD**.

- If the BOARD revision is *older* than the FILE version it indicates:
  - A new version of IDEA was recently installed on an older system, or,
  - An older AccuStream board was installed in a newer system.

The recommended action is to update the board to the newest Gate Array firmware file by selecting: OK, and following the prompts.

- DO NOT** shut down or abort the update while in progress.
- Once the update is complete. Power down the system completely, and reboot the system.

- If the BOARD revision is *newer* than the FILE version it indicates:
  - A new AccuStream board was recently installed on an older system, or,
  - An older AccuStream board was installed in a newer system.

The recommended action is to update the IDEA software to the newest revision.  
Or, if not practical / feasible to update IDEA software revision, to eliminate the mismatch Gate array message, replace the existing older gate array firmware files, with the latest IDEA files.  
-Updating the files will eliminate the dialog message, and preserve the latest board firmware.

-Only the specific board files need to be replaced.  
-The files are located at the default location of:  
**C:\Program Files\Foresight\IDEA\Iseries\** directory.

The specific files are:

AccuStream Express board series:	AccuStreamExpress.JBC
AccuStream HD+ board series:	AccuStreamExpressHD.JBC
AccuStream 1000 board series	AS1000.rpd
AccuStream 2000 board series	AS2000.rpd

It is not recommended to downgrade the newer board revision unless IDEA software or file updates are not allowed.


Please contact Foresight support [BD-SUPPORT@fi-llc.com](mailto:BD-SUPPORT@fi-llc.com), 978-458-4624 x244 for additional information.

### **DVI EDID Programming:**

=====

In DVI mode, the AccuStream boards act as a destination device, similar to a standard DVI LCD / Monitor. As such, the AccuStream communicates with the DVI or HDMI source using EDID (Extended Display Identification Data). The default native AccuStream EDID resolution parameters can be changed with an included IDEA EDID utility.

- To invoke the EDID program, go to:  
**C:\Program Files\Foresight\IDEA\Utilities\**
- Run the **DVI\_Config.exe** program.
- Select the interface, DVI 1 or DVI 2 (HDMI input).
- Select "FROM FILE",
- Choose the desired default native resolution from the selections.



## Video Streaming:

- =====
- \* Video stream rates are dependent on several factors beyond the AccuStream board.
  - \* The AccuStream Express boards can run in PCIe x4, x8 and x16 slots.
  - \* System processor, memory & disk speed all contribute to transfer rate speeds.
  - \* Below are transfer rates to memory on “typical” PCIe 1.0 x4 systems (500-700MB/s). and PCIe 2.0 x4 systems (1000-1300MB/s).
- Your performance may vary on slower machines.

RESOLUTION	STREAM to MEMORY ( PCIe x4 bus)
1600x1200x60	60 fps
1280x1024x60	60 fps
1024x768x60	60 fps
1920x1080x30	30 fps
1920x1080x60	60 fps

\* For fastest video streaming, use computers with a PCIe x4 bus or higher,

1GB of more memory and a SATA Raid striped disk or SSD sub-system is recommended for best performance when streaming to disk.

**Part numbers:**

=====

IDEA disk, P/N 042700-344

AccuStream Express 170	034000-100
AccuStream Express 75	034000-175
AccuStream Express 50	034000-150
AccuStream Express HD+	035000-100
AccuStream Express HD 75+	035000-175
AccuStream Express SD 50+	035000-150
AccuStream Express HD+C	036000-100
AccuStream Express HD 75+C	036000-175
AccuStream Express SD 50+C	036000-150
AccuStream 1000	037000-100
AccuStream 1000 LF	037000-175
AccuStream 1000 SDI	037000-200
AccuStream 2000	038000-100
AccuStream 2000 LF	038000-175
AccuStream 2000 SDI	038000-200

All boards are ROHS compliant

Typical **maximum** video capture formats:

See our product selection chart at: <http://www.fi-llc.com/boards/ProductsSelectionChart.php>

All 75 and LF series - Analog & DVI ,  
- VGA 1024x768x70 (75 MHz),  
- HDTV 1080i30, interlaced (74.25 MHz), 720p60 (74.25 Mhz)

All 50 series - Analog & DVI,  
- HDTV 480p60 (27 MHz)  
- VGA 800x600x70 (45.5MHz)  
- RS170 (12 MHz),  
- PAL (14 MHz)

All Others - Analog & DVI,  
- VGA 1600x1200x60, 1900x1200x60, (162 MHz),  
- HDTV 1080p60 (148.5 MHz)

**Power & Operating Temperatures**

=====

\*AccuStream Power consumption:

- AccuStream Express 170/75/50 = 15 watts to 20 watts
- AccuStream Express HD+/HD 75+/SD 50+ = 15 watts to 20 watts
- AccuStream 1000 = 8 watts
- AccuStream 2000 = 10 watts

\* Operating temperatures:  
10 to 50 degrees C

\* Humidity:  
10% to 90% non-condensing

\* Storage Temperature:  
0 to 70 degrees C

=====

For additional information or assistance, contact Foresight Imaging Technical Support at:

Email: [BD-Support@fi-llc.com](mailto:BD-Support@fi-llc.com)

Phone: + 978 458-4624 x244

Fax: + 978 458-5488

=====